

## **APPLICABLE REQUIREMENT: RULE 331 - WIPE CLEANING**

### **ALLOWABLE EMISSIONS:**

N/A

### **OPERATIONAL LIMITATIONS/STANDARDS:**

- 1) All cleaning-solvent, including solvent soaked materials, shall be kept in closed leakfree containers that are opened only when adding or removing materials. Rags used for wipe cleaning shall be stored in closed containers when not in use. Each container shall be clearly labeled with its contents.

[County Rule 331 §301.1] [SIP 331 §301]

- 2) If any cleaning-solvent escapes from a container, the permittee shall wipe up or other wise remove immediately if in accessible areas and for areas where access is not feasible during normal production, remove as soon as reasonably possible.

[County Rule 331 §301.2]

### **MONITORING/RECORDKEEPING:**

The Permittee shall maintain:

- 1) A current list of coatings, adhesives, makeup solvents, and any other VOC-containing materials; state the VOC content of each in pounds per gallon or grams per liter.

[County Rule 331 §501.1 a] [SIP 331 §501]

- 2) Monthly records of the amount of each cleaning-solvent used shall be updated by the end of month for the previous month. Show the type and amount of each make-up and all other cleaning-solvent to which these permit conditions are applicable.

[County Rule 331 §501.2 a] [SIP 331 §501]

### **REPORTING:**

The Permittee shall include the following information in each semi-annual compliance report;

- 1) a summary of the listed cleaning-solvents currently used at the facility and state the VOC-content of each in pound per gallon of material or grams per liter of material;
- 2) the quantity of each cleaning solvent used during the reporting period;
- 3) certify that monthly recordkeeping was performed as directed in the monitoring/recordkeeping requirement #2 above; and
- 4) any new or updated material safety data sheets (MSDS) that may have been obtained during the period.

[County Rule 210 302.1.e.(1)]